



Vehicle History Report

This report covers

- ✓ Ownership history
- ✓ Full service & maintenance records
- ✓ Accident & repair history
- ✓ Original OEM-installed features & specifications.

 **GJ 05 AI XXXX**

Maruti Suzuki Swift

2020i M Sport | 2020 | Manual | Petrol

 3 Challans pending [Clear challans >>](#)

Generated on 7 Dec, 2024

Inspection report

Ownership details

Ownership number: **1**

Type of owner: **Private**

Registration year: **2015**

Registration state: **Gujarat**

Fitness validity: **30 Sep, 2024**




Hypothecation & financier name: **True & HDFC Bank Ltd.**

PUC validity: **30 Sep, 2024**


Insurance validity & Type: **12 Dec, 2024 & comprehensive**

Past service records

Viewing the service history from authorised workshops helps assess the car's maintenance, check for any accidents, plan future care, and build confidence in its reliability and boost confidence in ownership.

 Last odometer reading (km at OEM) 1,00,000 Km	 Total loss reported No	 Accidental history Yes
------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------

Service & maintenance summary




This vehicle is serviced regularly

The car has been serviced 10 times in 5 years, with no gap exceeding 9 months.

Vehicle Details	Value	Remark
Total services at authorised service centre	6	✓
Last service at authorised service centre	20 Oct, 2024	✓
Structural damage	No	!
Airbag deployment	No	✓
Flooded car	No	✓
Odometer tampering	Yes	!
Gear/Transmission repair	No	!


Odometer Readings

METHODOLOGY Odometer tampering is identified if the next service record has a lower odometer reading than the previous one.




Odometer has been tampered once

The odometer has been tampered 01 time till now before the 7th service of the car. Since the odometer reading went down from S6 to S7.



Accident history



Major and minor accident reported in this car


There have been 6 major and minor accidents reported for this car.

Service records

Service visit number	Service date	Odometer reading (Kms)	Part details
S1	8 Jan, 2023	5,000	Spark Plug, Air Filter, Brake Oil, Grease Caliper Assy, Coolant, Boot Shift Lever (Black), Plug Oil Drain Work, Gear Knob, Brake Fluid GC1500AA (500 ML Pack)
S2	9 Mar, 2023	10,000	Engine oil replaced, Air filters replaced, Wheel Balancing & Alignment
S3	15 Jun, 2023	20,000	Bulbs change
S4	20 Nov, 2023	30,000	Engine oil replaced, Air filters replaced, Wheel Balancing & Alignment
S5	21 Jan, 2024	50,000	Engine oil replaced, Air filters replaced, Wheel Balancing & Alignment
S6	19 Mar, 2024	1,00,000	Engine oil replaced, Air filters replaced, Wheel Balancing & Alignment
S7	21 Jan, 2024	1,50,000	DCT - ECM Flashing
S8	20 Jul, 2024	1,75,000	Spark Plug, Air Filter, Brake Oil, Grease Caliper Assy, Coolant, Boot Shift Lever (Black), Plug Oil Drain Work, Gear Knob, Brake Fluid GC1500AA (500 ML Pack)


OEM installed features & specs

Understanding the features and specifications of the **Maruti Suzuki Swift** is essential to ensure it aligns with your preferences, needs, and lifestyle, helping you find the perfect automotive match.




Power window

Front & rear



Airbags

04



Seating capacity

05

Safety

Parameters	Metric
Front Fog Lights	Yes
ISOFIX-Child Seat Anchor Points	Yes
Anti-lock Braking System (ABS)	No
Central Locking	Keyless Entry
Rear Defogger	Yes
Airbags	04

Fuel & performance


Parameters	Metric
Max power (bhp)	81.80
Max torque (Nm)	114.7
Fuel tank capacity (lit)	24
Emission Standard	BSIV

📶 Entertainment & communication


Instrument panel type
Analogue & digital

360 degree camera
Yes


Speaker brand
JBL



✨ Interior & exterior



Dimensions & capacity



Engine, transmission & brakes


Parameters	Metric
Gear Box- No. of Gears	04
Displacement (cc)	1800
Transmission type	Manual
Cylinders	02
Break type (rear)	Drum
Break type (front)	Drum
Number of disc brakes	02

Comfort & convenience

Parameters	Metric
Seat upholstery (cc)	1800
Auto climate control	Yes
Wireless charging pad	Yes
Steering wheel material	Alloy & Synthetic Leather
Smart Card/Smart Key	Yes
Top model	Yes


Parking sensors

No




Rear AC

Yes




Power windows

Front & rear




Steering adjustment

Tilt & telescope




Driver seat adjustment

Manual




Cruise control

No




Air conditioner

Yes



Push button start

Yes





Vehicle Info

ALL-IN-ONE VEHICLE SOLUTION

Thank you for choosing us!

We appreciate your decision to care for your vehicle's safety and maintenance. Getting a proper inspection helps keep your car running well and gives peace of mind to you and your loved ones.

If you have any questions about the inspection report or need help, feel free to contact us. We're always here to support you and keep your car in great shape.

Thanks again for your trust!

Other services by



CHALLAN



SERVICE HISTORY



PERSONAL LOAN



FASTAG



Quick Scan, Instant Download



Managing everything about your car is now easier than ever!

Whether it's checking your service history, applying for a car loan, or securing the right insurance—we've got you covered, all in one place.



4.5+ Best Online Rating



KEEP IN TOUCH

Stay connected with us for updates, support, and more!



www.vehicleinfo.app



Disclaimer: We try our best to check vehicles carefully when we inspect them. However, Vehicleinfo isn't responsible if we miss something or if there are any hidden problems or incorrect details about the vehicle.